## XOTIC® PERFORMANCE



## INSTRUCTION MANUAL

4.8-6.2L CHEVROLET GM GEN III IV BALANCER BOLT KIT

PART NUMBER CP236 | 4.8L 5.3L 6.0L 6.2L

Clean all parts thoroughly, including bolt threads and the end of the crankshaft, to remove all dirt and foreign oils. Spread the assembly lubricant included in the package on the threads, underneath the bolt head, and the face of the washer that makes contact with the balancer bolt.

Then, install the bolt hand-tight, and tighten the bolts to **235 ft-lbs**.



## **NEED HELP?**

For technical support, please e
info@xotic-performance.com



WORKING ON AN EXCITING NEW PROJECT

Show off your costs on instagram and tag us to your picture for a charce to be featured TXOT (CPERFORMANICE)

DOC REF<sub>0</sub>2025.05.26